

Attachment 3 – Burnaby Lake Southeast Greenway Current Condition

Overview map



1. Section 1 - At pavement start, looking west



2. Section 1 - West end, looking west



3. Section 1 - Middle looking west



4. Section 1 - East end, looking west



5. Section 1 – Mid/east end, looking west



6. Section 1 - East end- truck rated bridge, looking east



7. Section 1 - 2 Boundary at BCH structure service vehicle turnaround, looking west



8. Section 2 - Middle, existing culverts, looking east



9. Section 2 - 3 Boundary, looking west



10. Section 3 – Middle, looking west



11. Section 3 – 4A Boundary, looking south, Hwy 1 in background



12. Section 4A – Looking south at Section 3 with Hwy 1 in background



13. Section 4A – Middle, looking south west



14. Section 4A – At parking lot looking southwest



15. Section 4A – Avalon at park entrance looking southwest



16. Section 4A – Avalon at MV Office, looking southwest



17. Section 4A – Avalon at MV office, looking northeast to Cariboo

